

Job Information

Job #:	97218				Date:	September 29, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Phelps Fan	Motor#:

Name Plate Information

Siemens	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:	125
	Model#:	Type: SD100	Service Factor:	1.15
444T	Rated RPM:	1785	Rated Voltage:	460
3	Rated Amps:	143	Cycles:	60
	444T	Model#: 444T Rated RPM:	(ODP) Model#: Type: SD100 444T Rated RPM: 1785	(ODP)

Special design: No

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



460

AC Electrical Inspection

Megs at reassembly:	Good	Surge at reassem	nbly: (Good	Hi-pot reassembly:	Good			
Winding Resistance I	Winding Resistance Incoming								
Phas	ses A to B	Phases B to C		Phases C to A	Resistive imbala	ance			
Outgoing									
Test Run InspectionDateSeptember 29, 202					0				
Yes I ha	Yes I have merged this motor and verified that all electrical tests are complete!								
Power Supply									
	Pha	ase A	Phase E	3	Phase C				

461

Temperatures: (Degrees Fahrenheit)				
No Load Current	46.5	46.2	45.4	

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

460

Temperature rise at the end of test run should be less than 2° every five minutes.

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

No Load Voltage



MILLINGTON, TN LITTLE ROCK, AR

Test Run Inspection (Continued)

Ambient Temp:

TIME	DE	Degree Change	ODE	Degree Change
START:				
5 MIN:				
10 MIN:				
15 MIN:				
20 MIN:				
25 MIN:				
30 MIN:				
35 MIN:				
40 MIN:				
45 MIN:				
50 MIN:				
55 MIN:				
60 MIN:				



Test Run Inspection (Continued)

Vibration Data: In./Sec-Peak	(Readings should be less than .08 In/Sec Peak)			
	Horizontal	VDE	Axial	
DE	0.02	0.03	0.03	
ODE	0.04	0.03	0.03	

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

Additional photos









Yes, the shaft has been isolated for delivery.

Service Tech name:

Terrence Holland

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301