

Job Information

Job #:	94188				Date:
Priority:	_	Authorized OT:	No	Authorized by:	

Customer Information

Name:	AFT	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	BAREC VARNOST	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type image
Serial#:		Model#:	3KTC180M-2	IN COLUMN
Service Factor:		Frame:	180M	
Horsepower/kW:	26KW	Rated RPM:	3525	N.W. Sa
Rated Amps:	71/41	Rated Voltage:	278/480	
Phase:	3	Cycles:	60	
Special design:	No			

Nameplate

DE

ODE

F1

. 16

F2





Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	Yes	Contaminant Image:	
Type of grounding device:	Aegis Ring		
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6310 ZZ C3
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6310 ZZ C3
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	N/A
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	N/A
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type: Seals DE size:	Other	Seals Image:	
Seals DE (inbound) condition :			T
Seals ODE type:	Labyrinth	Seals Image 2:	6
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	Me



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:




Water jacket: Ok



Fan: Ok







Motor Mount Position:

Horizontal/Foot mount

Missing parts?

J-Box cover	O-rings
HH cover	Glands

🔽 None

J-Box

Endbell type:

Single piece

Endbell Image:



Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)		Does Air Gap Meet Customer or EASA spec(<10% variation)?
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection


Number of leads:	6	Terminal Markings:	1-6	
Length of leads:		REF: NEMA Stds Markings Identifie	a. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White	5-Black 6-No color assigned	P1-No color assigned P2-Brown
Lead condition:	-	3-Orange 4-Yellow	7-No color assigned 8-Red	
Lug type:		Connections As Rec	ceived: 480	
Lug Condition:	Good	Т	erminal	Lugs
Lug size:		ALE.		
Lug Attachment:	Acceptable			

Core

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Windin	g image	Winding Therma	I Protection:	Yes
Winding condition :	Solid				ctorAnalyzar 2	SCILLEICH L
Winding Thermal Protection DE:	Good	- Alexandre			Productivno diversional diversion diversional diversional diversionad diversionad diversio	ed disabled ed disabled 50 -E-00009900 - 500 F37 50 - 500 50 - 500 50 - 500 50 - 500 50 - 500 50 - 500 50 - 500 500 500 500 500 500 500 500
Winding Thermal Protection ODE:	Good					
Stator test results:	Salvageable					
Megs incoming: Goo	d	Surge incoming:	Good	Hi-pot in	coming: G	ood
Winding Resistance In	coming					
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive imb	alance
Incoming 0.28	3	0.284	0.28	3	0.3	
Leads/jumpe			Lead ju	ımper Image:		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Replace Bearings ,Aegis Ring wash and bake

Service Tech name:

Robert Wiley

Service Tech signature:

Robers Willer

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301