

### **Job Information**

Job #:	94245				Date:	May 17, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

# **Customer Information**

Name:	Delta Plastics	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

# Name Plate Information

Manufacturer:	Allen Bradley	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:	6570703	Model#:		
Service Factor:		Frame:		
Horsepower/kW:	600	Rated RPM:	1780	
Rated Amps:	667	Rated Voltage:	460	
Phase:	3	Cycles:	60	
Special design:	Yes			

Nameplate

DE

ODE

F1

F2

Тор













WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Dirt
Shaft rotation:	—	Contaminant(s) Amt:	Quart
Shaft grounding device present?:	Yes	Contaminant Image:	
Type of grounding device:	Aegis		
Shaft runout(TIR-Inbound):	.001"		
Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	6219ZZ
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	6316 hybrid
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

#### Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254 Bearing Retainer Image



**Thermal Protection** 

Not Available



# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	N/A
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	N/A
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A	Seals Image:	
Seals DE size:			Not Available
Seals DE (inbound) condition :			
Seals ODE type:	N/A	Seals Image 2:	Net
Seals ODE size:			Not Available
Seals ODE (inbound) condition			
Shaft damage cause:	Keyway bad	Shaft Image:	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **Mechanical Inspection (Continued)**

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A

Fan: N/A Frame cond.: Good







Motor Mount Position:	Horizontal/F	oot mount	Endbell type:	Single piece	
Missing parts?			Endbell Image:		
J-Box cover	O-rings	J-Box			
HH cover	Glands	None None			
Other missing parts					



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



502

# **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single P	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

# **AC Electrical Inspection**

Number of leads:	6	Terminal Markings:				
Length of leads:	20"	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	Good	4-Yellow	8-Red			
Lug type:		Connections As Re	ceived:			
Lug Condition:	_		Terminal	Lugs		
Lug size:			Not			
Lug Attachment:	_		ailable			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type:	Cast Aluminum		Rotor
Rotor Condition:	Ok	Num rotor bars: Num broken bars:	-
Rotor Test Results			
Visual: Pass	Gi	rowler: Pass	Single phase: Pass
Stator type:	Factory	If other, stator	type:
Stator condition:	Ok	If other, stator cond	ition:
Failure location:	In slot	If other, stator fa	ilure:
Stator Image:		Failure Im	<sup>nage:</sup> Not Available

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Winding o	color:	Like new	Winding	g image	Winding Therma	I Protection:	Yes
Winding condi	tion :	Solid				71	
Winding The Protectior		_					
Winding Thermal Protection ODE:							
Stator test res	sults:	Salvageable					
Megs incoming:	Goo	d	Surge incoming:	Good	Hi-pot in	coming: G	ood
Winding Resist	ance In	coming					
	Phas	es A to B	Phases B to C	Phase	es C to A	Resistive imb	alance
Incoming	10.2	277	10.297	10.28	39	0.1	
Lea	ds/jump	ers: Ok		l ead iur	nper Image. :		
						No	+
If other, lead	ds/jump	ers:				No Availa	able

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

#### **Component Failure**

Checks good electrically, DE keyway worn

#### **Cause of Failure**

Water in motor

#### Comments

Service Tech name: Lynn McDonald

Service Tech signature:

gr Nitold

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301