

Job Information

Job #: 136086 Date: January 15,

2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Xylem dewatering solutions Motor#:

Name Plate Information

Manufacturer: Garmin rupp Enclosure: Open Drop Proof Horsepower/kW: 10

(ODP)

Serial#: 1634812 Model#: S4c1-e10 Service Factor:

Frame: Rated RPM: Rated Voltage: 460

Phase: 3 Rated Amps: 34/17 Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: .7875

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: .7875

Retainer condition: Good



Mechanical Inspection (Continued)

Seals DE condition: None Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Shaft damage: OK None

Seals ODE type: Slinger

Bushings/sleeves DE: Other Seals ODE size:

Bushings/sleeves ODE: Other Seals ODE (inbound) condition: 1.376

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: Foot flatness: **Pass**

Endbell DE insulated?: No

> variation)? Endbell ODE size: 1.8504

> > Yes

Does Air Gap Meet Customer or EASA spec(<10%

No

Conclusion

Service Tech name: Billy

Endbell ODE insulated?:

Service Tech signature: