

## **Job Information**

Job #: 136106 Date: February 28,

2018

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: Ktg Motor#:

**Name Plate Information** 

Manufacturer: Abb Enclosure: Totally Enclosed Horsepower/kW: 1050kw

Fan Cooled

Serial#: 4586528 Model#: Hxr500lq6 Service Factor:

Frame: 500l Rated RPM: 999.9 Rated Voltage: 460

Phase: 3 Rated Amps: 1545 Cycles: 50.2

Special design: No

**Mechanical Inspection** 

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6326

Shaft runout(TIR-Inbound): .oo1 Bearing ODE Size: 6324

Retainer condition: Good



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: 0

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 0

Seals ODE condition: Shaft damage: Worn OK

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 11.026 Foot flatness: **Pass** 

Endbell DE insulated?: No

> Does Air Gap Meet Customer or EASA spec(<10% Endbell ODE size: 10.240

variation)?

Endbell ODE insulated?: No Yes

## Conclusion

Service Tech name: Billy Mays

Service Tech signature: