

## **Job Information**

Job #: 136440 Date: June 8, 2018

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: CHEMOURS Motor#:

**Name Plate Information** 

Manufacturer: SIEMENS Enclosure: Totally Enclosed Horsepower/kW: 250

Fan Cooled

Serial#: 1-5113-38799-1-1 Model#: Service Factor: 1.0

Frame: 507US Rated RPM: 1780 Rated Voltage: 460

Phase: 3 Rated Amps: 283 Cycles: 60

Special design: No

**Mechanical Inspection** 

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6315ZZ SKF

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: 6315ZZ SKF

Retainer condition: Good



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .000

Seals DE size: 3.561 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 2.749 .000

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size: 3.561

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition: 2.749

> Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 6.304 Foot flatness: **Pass** 

Endbell DE insulated?: No

> variation)? Endbell ODE size: 6.300

Does Air Gap Meet Customer or EASA spec(<10%

Endbell ODE insulated?: No Yes

## Conclusion

Service Tech name: Billy mays

Service Tech signature: