

Job Information

Job #: 137093 Date: August 3, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: ASSOCIATED ELECTRICAL COOP Motor#:

Name Plate Information

Manufacturer: HYUNDAI Enclosure: Weather Protected Horsepower/kW: 2750

II (WPII)

Serial#: 12056RMH242002 Model#: HRP7-505-28E Service Factor: 1.0

Frame: 500 Rated RPM: 3600 Rated Voltage: 4000

Phase: 3 Rated Amps: 338.6 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 63451/2-54

Shaft runout(TIR-Inbound): .OO1 Bearing ODE Size: 61755/4-16

Retainer condition: Good



Mechanical Inspection (Continued)

Seals DE condition: None Brg. Seats DE: Good

Seals DE type: Labyrinth If DE undersized, amt.: .000

Seals DE size: 3.932 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 3.932 .000

Seals ODE condition: Shaft damage: OK None

Seals ODE type: Labyrinth

Bushings/sleeves DE: Ok Seals ODE size: 3.933

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition: 3.933

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: Foot flatness: **Pass**

Endbell DE insulated?: Yes

> Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE size:

Endbell ODE insulated?: No Yes

Conclusion

Service Tech name: **BILLY MAYS**

Service Tech signature: