

Job Information

Job #:	137188				Date:	May 22, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Univ. Of memphis /physical plant and planning	Motor#:
-------	-----------------------------------------------	---------

Name Plate Information

U.s	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	25
C0-R900A-M	Model#:	R900A	Service Factor:	
284T	Rated RPM:	1775	Rated Voltage:	460
3	Rated Amps:	29.2	Cycles:	60
	C0-R900A-M 284T	C0-R900A-M Model#: 284T Rated RPM:	Fan Cooled CO-R900A-M Model#: R900A 284T Rated RPM: 1775	Fan CooledC0-R900A-MModel#:R900AService Factor:284TRated RPM:1775Rated Voltage:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6310D
Shaft runout(TIR-Inbound):	.001	Bearing ODE Size:	6210D
Retainer condition:	Good		

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	.000
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :	1.965	If ODE undersized, amt.:	.000
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :	1.965	Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	4.331	Foot flatness:	Pass
Endbell DE insulated?:	No	Door Air Can Moot Cu	stomer or EASA spec(<10%
Endbell ODE size:	3.544	variation)?	
Endbell ODE insulated?:	No	Yes	

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254