

Job Information

Job #:	137593				Date:	August 20, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

UNILEVER MFG. Name: Motor#:

Name Plate Information

KIUYNER	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	40
B12018-3S	Model#:	N/A	Service Factor:	1.15
32XL	Rated RPM:	1765	Rated Voltage:	230/460
3	Rated Amps:	96.2/46.1	Cycles:	60
	B12018-3S 32XL	B12018-3S Model#: 32XL Rated RPM:	Fan Cooled B12018-3S Model#: N/A 32XL Rated RPM: 1765	Fan CooledB12018-3SModel#:N/AService Factor:32XLRated RPM:1765Rated Voltage:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Damaged	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6311
Shaft runout(TIR-Inbound):	.001	Bearing ODE Size:	6211

Retainer condition:

Good

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254





Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Other	If DE undersized, amt.:	.00
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	.00
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	4.725	Foot flatness:	Pass
Endbell DE insulated?:	No	Doos Air Gan Moot Cus	tomor or EASA space/~10%
Endbell ODE size:	3.937	variation)?	tomer or EASA spec(<10%
Endbell ODE insulated?:	No	Yes	

Conclusion

Service Tech name: BILLY MAYS

Service Tech signature:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254