

## **Job Information**

Job #: 137711 Date: July 17, 2018

Priority: — Authorized OT: No Authorized by:

## **Customer Information**

Name: INCA PRESSWOOD PALLETS, INC. Motor#:

#### **Name Plate Information**

Manufacturer: N/A Enclosure: Totally Enclosed Horsepower/kW: 7.5

Fan Cooled

Serial#: R82BV132M-4 Model#: 10660004.9.02.030 Service Factor: ; .85

01

Frame: 132M Rated RPM: 1740/89 Rated Voltage: 480

Phase: 3 Rated Amps: 12.3 Cycles: 60

Special design: No

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: — Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6209

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: 6309

Retainer condition: Good



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .000

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: .000

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.937 Foot flatness: **Pass** 

Endbell DE insulated?: No

Endbell ODE insulated?:

Does Air Gap Meet Customer or EASA spec(<10% variation)? Endbell ODE size:

Yes

3.747

Conclusion

Service Tech name: **BILLY MAYS** 

Service Tech signature:

No