

## **Job Information**

Job #: 138160 Date: September 26,

2018

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: AMERICAN MARSH Motor#:

**Name Plate Information** 

Manufacturer: U.S. Enclosure: Totally Enclosed Horsepower/kW: 15

Fan Cooled

Serial#: N/A Model#: N/A Service Factor: 1.15

Frame: 254T Rated RPM: 1780 Rated Voltage: 230/460

Phase: 3 Rated Amps: N/A Cycles: 60

Special design: No

**Mechanical Inspection** 

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Damaged Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6208

Shaft runout(TIR-Inbound): .001 Bearing ODE Size: 6206

Retainer condition: Good



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: .005

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: .000

Seals ODE condition: Shaft damage: OK Worn

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.4 Foot flatness: **Pass** 

Endbell DE insulated?:

variation)? Endbell ODE size:

Yes

Does Air Gap Meet Customer or EASA spec(<10%

2.441

Conclusion

Service Tech name: **BLM** 

Endbell ODE insulated?:

Service Tech signature: