



MILLINGTON, TN

LITTLE ROCK, AR

## Job Information

Job #: 94158

Date: April 17, 2018

Priority: —

Authorized OT: No

Authorized by:

## Customer Information

Name: Energy

Motor#:

## Name Plate Information

Manufacturer:	Enclosure :	Open Drop Proof (ODP)	Horsepower/kW:
Serial#:	Model#:		Service Factor:
Frame:	Rated RPM:		Rated Voltage:
Phase:	Rated Amps:		Cycles:

Special design: No

## Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6207ZZ

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6206ZZ

Retainer condition: —

**WEST TENNESSEE**

7030 Ryburn Drive  
Millington, TN 38053  
Phone 901-873-5300  
Fax 901-873-5301

**CENTRAL ARKANSAS**

6812 Lindsey Rd.  
Little Rock, AR 72206  
Phone 501-375-9178  
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

## Mechanical Inspection (Continued)

Seals DE condition : None

Brg. Seats DE: Good

Seals DE type: N/A

If DE undersized, amt.:

Seals DE size:

Brg. Seats ODE: Good

Seals DE (inbound) condition :

If ODE undersized, amt.:

Seals ODE condition : None

Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok

Seals ODE size:

Bushings/sleeves ODE: Ok

Seals ODE (inbound) condition :

Endbell fits/damage: Good

Foot/Flange condition: Ok

Endbell DE size: 2.8353

Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(&lt;10% variation)?

Endbell ODE size: 2.4614 BAD

Endbell ODE insulated?: No

—

## Conclusion

Service Tech name: Robert Wiley

Service Tech signature: