



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 94160

Date: April 18, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: ENTERGY

Motor#:

Name Plate Information

Manufacturer: Westinghouse Enclosure : Totally Enclosed Non-Ventilated Horsepower/kW: 1.1

Serial#: Model#: Service Factor:

Frame: Rated RPM: Rated Voltage:

Phase: Rated Amps: Cycles:

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: 6207ZZ

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6206ZZ

Retainer condition: —

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Worn	Shaft damage:	OK
Seals ODE type:	N/A	Bushings/sleeves DE:	Ok
Seals ODE size:		Bushings/sleeves ODE:	Ok
Seals ODE (inbound) condition :		Foot/Flange condition:	Ok
Endbell fits/damage:	Bad	Foot flatness:	Pass
Endbell DE size:	2.8347 GOOD	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell DE insulated?:	No		
Endbell ODE size:	2.4844 BAD		
Endbell ODE insulated?:	No		

Conclusion

Service Tech name: Robert Wiley

Service Tech signature: