

Job Information

Job #:	94198				Date:	April 24, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Entergy White Bluff	Μ	otor#:

Name Plate Information

Limitorque	Enclosure :	Totally Enclosed Non-Ventilated	Horsepower/kW:	1
B447026-NE	Model#:	B71Q2163M-XG	Service Factor:	1.0
M56	Rated RPM:	1700	Rated Voltage:	230/460
3	Rated Amps:		Cycles:	60
	B447026-NE M56	B447026-NE Model#: M56 Rated RPM:	Non-Ventilated B447026-NE Model#: B71Q2163M-XG M56 Rated RPM: 1700	Non-VentilatedB447026-NEModel#:B71Q2163M-XGService Factor:M56Rated RPM:1700Rated Voltage:

Special design: Yes

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	No
Type of grounding device:		Bearing DE Size:	6203ZZ
Shaft runout(TIR-Inbound):		Bearing ODE Size:	6203ZZ

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254





Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt .:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	1.5758	Foot flatness:	N/A
Endbell DE insulated?:	No	Doos Air Gap Moot Cus	stomer or EASA spec(<10%
Endbell ODE size:	1.5758	variation)?	
Endbell ODE insulated?:	No	_	

Conclusion

Service Tech name:

Lynn McDonald

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254