

Job Information

Job #: 94208 Date: April 21, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Flakeboard Motor#:

Name Plate Information

Manufacturer: Toshiba Enclosure: Totally Enclosed Horsepower/kW: 350

Fan Cooled

Serial#: Service Factor:

Frame: 5010US Rated RPM: 1185 Rated Voltage: 460

Phase: 3 Rated Amps: 416 Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6320

Shaft runout(TIR-Inbound): Bearing ODE Size: 6320

Retainer condition: Good



Mechanical Inspection (Continued)

Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 8.4673 Foot flatness: Pass

Endbell DE insulated?: No

Endbell ODE size:

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No –

8.4670

Conclusion

Service Tech name: Lynn McDonald

Service Tech signature:

CENTRAL ARKANSAS 6812 Lindsey Rd.

Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

7030 Ryburn Drive

WEST TENNESSEE

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254