



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 94295

Date: May 17, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: St Gobain

Motor#:

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	300
Serial#:	A1209272022	Model#:	Z44G4243	Service Factor:	1.15
Frame:	449TDZ	Rated RPM:	1785	Rated Voltage:	460
Phase:	3	Rated Amps:	334	Cycles:	60

Special design: Yes

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Damaged

Bearings Retainer: Yes

Type of grounding device:

Bearing DE Size: NU222

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6318

Retainer condition: —

WEST TENNESSEE
7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS
6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE condition : None

Brg. Seats DE: Good

Seals DE type: N/A

If DE undersized, amt.:

Seals DE size:

Brg. Seats ODE: Good

Seals DE (inbound) condition :

If ODE undersized, amt.:

Seals ODE condition : None

Shaft damage: Salvageable

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Bushings/sleeves ODE: Ok

Seals ODE (inbound) condition :

Endbell fits/damage: Bad

Foot/Flange condition: Ok

Endbell DE size: 7.8750 good

Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE size: 7.4823 bad

Endbell ODE insulated?: No

—

Conclusion

Service Tech name: Lynn McDonald

Service Tech signature: