

Job Information

Job #: 94386 Date: June 12, 2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Democrat Printing Motor#:

Name Plate Information

Manufacturer: Siemens Enclosure: Totally Enclosed Horsepower/kW: 41/44/44

Non-Ventilated

Serial#: 1PH7167-2EG330B Model#: YFV846071301004 Service Factor:

DB8

Frame: Rated RPM: 2000/2300/2650 Rated Voltage: 350/398/459

Phase: 3 Rated Amps: 89/85/77 Cycles: 67/77/89

Special design: Yes

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6313 2RS

Shaft runout(TIR-Inbound): Bearing ODE Size: 62122RS

Retainer condition: —



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: Fair If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: Foot flatness: Pass

Endbell DE insulated?: No

Endbell ODE size:

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No —

Conclusion

Service Tech name: Lynn McDonald

Service Tech signature:

WEST TENNESSEE CENTRAL ARKANSAS
7030 Ryburn Drive 6812 Lindsey Rd.

Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254