



MILLINGTON, TN

LITTLE ROCK, AR

Job Information

Job #: 94462

Date: July 6, 2018

Priority: —

Authorized OT: No

Authorized by:

Customer Information

Name: Cintas

Motor#:

Name Plate Information

Manufacturer: ABM

Enclosure : Totally Enclosed
Fan Cooled

Horsepower/kW: 3 kW

Serial#: F753510 0002

Model#:

Service Factor:

Frame:

Rated RPM: 109/1670

Rated Voltage: 277/480

Phase: 3

Rated Amps: 8.5/5.1

Cycles: 60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good

Bearings Retainer: No

Type of grounding device:

Bearing DE Size: 6210 ZZ

Shaft runout(TIR-Inbound):

Bearing ODE Size: 6307 ZZ

Retainer condition: —

WEST TENNESSEE

7030 Ryburn Drive
Millington, TN 38053
Phone 901-873-5300
Fax 901-873-5301

CENTRAL ARKANSAS

6812 Lindsey Rd.
Little Rock, AR 72206
Phone 501-375-9178
Fax 501-375-4254



MILLINGTON, TN

LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Other	If DE undersized, amt.:	
Seals DE size:	50-65-8	Brg. Seats ODE:	Good
Seals DE (inbound) condition :	Fair	If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	OK
Seals ODE type:	N/A	Bushings/sleeves DE:	Ok
Seals ODE size:		Bushings/sleeves ODE:	Ok
Seals ODE (inbound) condition :			
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok
Endbell DE size:	3.5434 good	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	Xxxx bad		
Endbell ODE insulated?:	No		

Conclusion

Service Tech name: Lynn McDonald

Service Tech signature: