

## **Job Information**

Job #: 94537 Date: July 20, 2018

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: AFT Motor#:

**Name Plate Information** 

Manufacturer: Baldor Enclosure: Totally Enclosed Horsepower/kW: 40

Fan Cooled

Serial#: B9040704 070 Model#: B377400 Service Factor:

Frame: 324HP Rated RPM: 1775 Rated Voltage: 230/460

Phase: 3 Rated Amps: 99/49.5 Cycles: 60

Special design: No

**Mechanical Inspection** 

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Damaged Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6311 ZZ

Shaft runout(TIR-Inbound): .0025 Bearing ODE Size: 6311 2RS

Retainer condition: —



## **Mechanical Inspection (Continued)**

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Slinger

Bushings/sleeves DE: Ok Seals ODE size:

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 4.7752 bad Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

pm McDondd

Endbell ODE size: 4.7257 ok variation)?

Endbell ODE insulated?: No —

## Conclusion

Service Tech name: Lynn McDonald

Service Tech signature:

WEST TENNESSEE CENTRAL ARKANSAS
7030 Ryburn Drive 6812 Lindsey Rd.
Millington, TN 38053 Little Rock, AR 72206

Phone 501-375-9178 Fax 501-375-4254