

Job Information

Job #:	94588				Date:	August 13, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:		Motor#:

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	200
Serial#:	X1104	Model#:		Service Factor:	1.15
Frame:	449TS	Rated RPM:	1190	Rated Voltage:	460
Phase:	3	Rated Amps:	225	Cycles:	60

Special design: No

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Other	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6318 ZZ
Shaft runout(TIR-Inbound):	.003"	Bearing ODE Size:	6318 ZZ
Retainer condition:	Good		

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Other	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Other	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok
Endbell DE size:	7.4810 good	Foot flatness:	Pass
Endbell DE insulated?:	No	Doop Air Con Moot Cu	stamor or EASA apool <10%
Endbell ODE size:	7.4820 bad	variation)?	stomer or EASA spec(<10%
Endbell ODE insulated?:	No	_	

Conclusion

Service Tech name:

Lynn McDonald

Service Tech signature:

Lyn McDuel

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254