

#### **Job Information**

Job #:	94759				Date:	September 28, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

# **Customer Information**

Name:	Flakeboard	Motor#	:

# **Name Plate Information**

Baldor	Enclosure :	Totally Enclosed Fan Cooled	Horsepower/kW:	75
CAT: M4316T	Model#:	14C51W288	Service Factor:	1.15
365T	Rated RPM:	1760	Rated Voltage:	230/460
3	Rated Amps:	176/88	Cycles:	60
	CAT: M4316T 365T	CAT: M4316T Model#: 365T Rated RPM:	Fan Cooled CAT: M4316T Model#: 14C51W288 365T Rated RPM: 1760	Fan CooledCAT: M4316TModel#:14C51W288Service Factor:365TRated RPM:1760Rated Voltage:

Special design: No

### **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Broken	Bearings Retainer:	Yes
Type of grounding device:	Aegis	Bearing DE Size:	6313/2RS
Shaft runout(TIR-Inbound):	N/A	Bearing ODE Size:	6312/2RS
Retainer condition:	Good		

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



### **Mechanical Inspection (Continued)**

Seals DE condition :	None	Brg. Seats DE:	Undersized
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	Replace
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	5.5128	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gan Meet Cu	stomer or EASA spec(<10%
Endbell ODE size:	5.1191	variation)?	
Endbell ODE insulated?:	No	_	

# Conclusion

Service Tech name:

Terrence Holland

Service Tech signature:



24.ll

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254