

4/12/2021 7:08:28 AM	°F	4/12/2021 7:08:37 AM
Sp2 Sp1 + +	128.0	
IR_1777.jpg S60 NTSC	21801575	DC_1778.jpg
Measurements		
Sp1		118.9 °F
Sp2		102.7 °F
Parameters		
Emissivity		0.95

Asset #2223

The infrared data indicates that the blade for phase B has a high resistance connection. This could be due to blade looseness or the blade could be dirty. Inspect, clean and check for proper seating of the blade in reciver.