



8/25/2021 7:01:12 AM



8/25/2021 7:01:21 AM



Measurements

Sp1	141.0 °F
Sp2	97.3 °F
Sp3	98.9 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates a high resistance connection on the line side of Phase B . Check the fuse clip for damage and tightness. Clean fuse holder and fuse blade. Replace if needed.