



8/11/2021 7:31:28 AM



8/11/2021 7:31:41 AM



Measurements

Sp1	130.0 °F
Sp2	126.8 °F
Sp3	121.7 °F
Sp4	113.5 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates that phase a high resistance connection on line and load side of CR 3018 indicating a possible loose wire connection or contacts going bad. Check contacts for damage, replace them as necessary tighten the wire to proper torque.