August 16, 2018

Date



### **Job Information**

Job #: 94360 Date: August 16, 2018

Priority: — Authorized OT: No Authorized by:

#### **Customer Information**

Name: Bryce Motor#:

### **Name Plate Information**

Manufacturer: Emerson Enclosure : Open Drop Proof

(ODP)

Serial#: Model#:

Service Factor: Frame:

Horsepower/kW: Rated RPM:

Volts 500 Volts 300
Armature Fields

Amps 105 Amps 1.9

# **Test Run Inspection**

Yes I have merged this motor and verified that all electrical tests are complete!

**Power Supply** 

Phase A Phase B Phase C

No Load Voltage 499 300

No Load Current 3.2 22

Fax 901-873-5301



### **Test Run Inspection (Continued)**

**Temperatures: (Degrees Fahrenheit)** 

Test run ball-bearing motors for 15 minutes.

Test run sleeve bearing motors for 60 minutes.

Temperature rise at the end of test run should be less than 2° every five minutes.

Ambient Temp:						
TIME	DE	Degree Change	ODE	Degree Change		
START:						
5 MIN:						
10 MIN:						
15 MIN:						
20 MIN:						
25 MIN:						
30 MIN:						
35 MIN:						
40 MIN:						
45 MIN:						
50 MIN:						
55 MIN:						
60 MIN:						

Fax 901-873-5301



## **Test Run Inspection (Continued)**

Vibration Data: In./Sec-Peak (Readings should be less than .08 In/Sec Peak)

	Horizontal	VDE	Axial
DE	0.08	0.03	0.02
ODE	0.06	0.02	0.02

Magnetic Center Measurements (Only Applies to Sleeve Bearing Motors)

Magnetic Center line distance from shaft shoulder

Magnetic Center line distance from all the way out mark

Magnetic Center line distance from all the way in mark

Total Motor End Float

### **Additional photos**







Yes, the shaft has been isolated for delivery.

Service Tech name: Robert Wiley

Service Tech signature:

ROSOTT Dilers