



8/11/2021 7:32:38 AM



8/11/2021 7:32:53 AM



Measurements

Sp1	132.3 °F
Sp2	121.7 °F
Sp3	121.3 °F

Parameters

Emissivity	0.95
Refl. temp.	49 °F

Infrared data indicates that the Fuse holder for phase B has a high resistance connection on the load side indicating a possible loose wire connection. Check for damage, replace as necessary tighten the wire to proper torque.