

Job Information

Job #:	142369				Date:	April 29, 2020
Priority:	_	Authorized OT:	No	Authorized	l by:	
Customer	Information					
Name:	Cleveland tramrail	Location:			Contact:	
Name Plat	e Information					
Manufacturer:	Cleveland			Ratio:	N/A	
Serial#:	N/A			Туре :	End truck	
Model#:	N/A			Horsepower/kW:		
Input Speed:				Output Speed:		
Application ID:				Coupling Type:		

Gearbox Visual Inspection

	Wear	Physical	Contaminants
Oil:	Unacceptable	Acceptable	Unacceptable
Gears:	Unacceptable	Unacceptable	Unacceptable
Seals:	_	_	_

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Gearbox Inspection (Continued)











WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301





Gearbox Inspection (Continued)

Environmental Conditions :	Severe/Hostile	Ambient Temperature :
Signs of excessive heat:	No	Humidity :
Signs of lubricant leaks:	No	Gearbox temperature :
Moisture present:	Yes	

Gearbox Inspection & Evaluation Checklist

1. Primary drive rotates input shaft in correct direction	Yes
2. Condition of machinery guards if present	Present/Acceptable
3. Condition of coupling guards	Not Present
4. Type of coupler	Two piece
5. Condition of coupler	Present/Acceptable
6. Coupling Alignment	
7. Condition of housing	Acceptable
8. Condition of mounting hardware	Acceptable
9. Breather vent (ventilator) installed	Not Present
10. Condition of piping & connections(if forced lube system installed)	Not Present

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Gearbox Inspection & Evaluation Checklist (Continued)

11. Condition of switches, alarms, heaters, coolers, or other devices	Present/Acceptable
12. Condition of inspection covers	Present/Acceptable
13. Condition of seals & bearings	Unacceptable
14. Gearbox oil level	N/A
15. Type & grade of specified lubricant	
16. Correct type & grade of specified lubricant	Unknown
17. Appearance of lubricant	Appears new
18. Free rotation of shafts	Yes
19. Condition of input shaft	Acceptable
20. Endplay of input shaft	
21. Condition of output shaft	Acceptable
22. Endplay of output shaft	

23. Gear backlash

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254 Acceptable



Gearbox Inspection & Evaluation Checklist (Continued)

24. Gear tooth condition	Acceptable
25. Degree of wear	Mild
26. Gear tooth contact	Acceptable
27. Identify type of gear tooth contact	
A. B. C.	A. Perfect contact - no modification needed B. Acceptable contact - Gear with end ease-off modification - slight crowning. C. Acceptable contact - Gear with crowning modification
	D. Acceptable contact - Gear shafts slightly off parallel
E.	E. NOT Acceptable contact - Gear shafts out of parallel
F.	F. NOT Acceptable contact - Gear shafts out of parallel
G.	G. NOT Acceptable contact - (if no lead modification present) gear and/or pinion miscut - correct parts
H.	H. NOT Acceptable contact - (if no lead modification present) gear and/or pinion miscut - correct parts

Typical Contact Patterns for Double Helical Gears

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Gearbox Comments

Replace bearings, remove rust from gears and case .

Conclusion

Service Tech name: Jesus

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301