

# LR Field Services

Prepared for Midsouth Steam Boiler

3805 Pointer Trail East  
Van Buren AR 72956

# Table of Contents

Balancing Report

1.0

---

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 11/22/2022

Powered by [INSPECTALL](#)

*Table of Contents*




Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Balancing Report

**Midsouth Steam Boiler**  
3805 Pointer Trail East  
Van Buren, AR 72956

*Performed By: Motor Shop LR 1  
Date Completed: 11/22/2022*

FolderID: 100580  
FormID: 15222255

<b>General</b>		
1. Job Number	<b>100580</b>	
2. Report Date	<b>11/22/2022</b>	
3. Customer	<b>MSSB / DarPro</b>	
<b>Balancing Report</b>		
4. Balance Type	<b>single plane overhung</b>	
5. Balance Operating Speed	<b>3580 RPM</b>	
6. Starting Measurements		
Left End	Right End	
<b>2.0853</b>	<b>1.2709</b>	
7. Balancing Specification	<b>.5</b>	
8. Finished Measurements		
Left End	Right End	
<b>0.3786</b>	<b>0.2782</b>	
9. List Parts Needed <i>7g weight</i>		
10. Service Technician		<b>David Maclin</b>
		

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.