




# **DANGER:**

UNLESS HOOK RAISES WHEN "UP" BUTTON IS PRESSED SEVERE HOIST DAMAGE AND A DROPPED LOAD MAY RESULT.

CORRECT IMPROPER HOOK DIRECTION BY INTERCHANGING MOTOR LEADS ORANGE (5) & RED (8).  
DO NOT CHANGE PUSHBUTTON WIRING.

# **WARNING**

THIS EQUIPMENT MUST BE EFFECTIVELY GROUNDED ACCORDING TO APPLICABLE CODES.

# **AVERTISSEMENT**

CET EQUIPMENT DOIT ETRE MIS A'LA TERRE EN ACCORDANCE AVEC LES NORMES EN VIGUEUR.

| NO. | CHANGE | DATE | ITL. | WIRING DIAGRAM                                  |
|-----|--------|------|------|-------------------------------------------------|
|     |        |      |      | 1 PHASE RECONNECTABLE, STEARNS REVERSING SWITCH |
|     |        |      |      | D.C. SOLENOID BRAKE                             |
|     |        |      |      | BUDGET ELECTRIC HOIST                           |
|     |        |      |      | SC. -----                                       |
|     |        |      |      | DR. 7/19/04                                     |
|     |        |      |      | DR. RITTER                                      |
|     |        |      |      | CK.                                             |
|     |        |      |      | SHEET 1 OF 4 SHEETS                             |
|     |        |      |      | 333171                                          |