




DANGER:

UNLESS HOOK RAISES WHEN "UP" BUTTON IS PRESSED SEVERE HOIST DAMAGE AND A DROPPED LOAD MAY RESULT. CORRECT IMPROPER HOOK DIRECTION BY INTERCHANGING INPUT POWER L1 AND L3 DO NOT CHANGE PUSHBUTTON WIRING.

WARNING:

THIS EQUIPMENT MUST BE EFFECTIVELY GROUNDED ACCORDING TO APPLICABLE CODES.

AVERTISSEMENT

CET EQUIPEMENT DOIT ETRE MIS A LA TERRE EN ACCORDANCE AVEC LES NORMES EN VIGUEUR.

NO.	CHANGE	DATE	ITL.	WIRING DIAGRAM	230 VOLT
				3 PHASE RECONNECTABLE	
				D.C. SOLENOID BRAKE	
				BUDGIT ELECTRIC HOIST	
				SC. -----	
				DA. 7/19/04	
				DR. RITTER	
				CK.	
				division of Columbus McKinnon Corporation Muskegon, Michigan 49443	
				SHEET 1 OF 4 SHEETS	
				333173	