LR Field Services

Prepared for ANTHONY TIMBERLANDS (12055)

111 SOUTH PLUM STREET BEARDEN AR 71720

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 103397 FormID: 21362276

Field Service Ticket

ANTHONY TIMBERLANDS (12055)

111 SOUTH PLUM STREET BEARDEN, AR 71720

Job Information		
1.	Hi-Speed Job Number	103397
2.	Asset Type	
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	
Service Call Details		
7.	Service Objectives	
8.	Services Performed	
	Took vibration data. Customer would not shut down the 4 saw mill motors to take data. Edger 2 and edger 1 me backwards. Edger 2 and edger 1 hydraulics are backwards.	otors are
9.	Service Technician Recommendations	
Approval Signatures		
10.	Service Technician Signature	Trevor Hall
11.	Customer Signature	Jd Gardner