LR Field Services

Prepared for Evonik(10512)

10300 Arch St. Pike Little Rock AR 72206

Table of Contents



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 102844 FormID: 20255323

Field Service Ticket

Evonik(10512) 10300 Arch St. Pike Little Rock, AR 72206

Job Information

1. Hi-Speed Job Number

102844

2. Asset Type

3. Make



















- 4. Model
- 5. Serial Number
- 6. Customer Asset ID/Asset Name

Service Call Details

- 7. Service Objectives
 - Balance fans
- 8. Services Performed

Balanced four fans

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.









Act 1 preheat fan. Started at 3.5 No identifier on fan mils. Ended at 0.5.

Fan 004. Started at 2.5. Ended Fan 004 at 0.5 and 0.2





No identifier. Started at 2.1 mils. Ended at 0.3 and 0.1

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature Trevor Hall

11. Customer Signature

Teddy Hernandez