



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 102863  
FormID: 20270991

**Union Pacific-Vine St 10945**

1020 N. Vine Street  
North Little Rock, AR

Shop

### Job Information



- |                        |              |
|------------------------|--------------|
| 1. Hi-Speed Job Number | 102863       |
| 2. Asset Type          | clutch brake |
| 3. Make                | P3           |



- |                                 |                |
|---------------------------------|----------------|
| 4. Model                        |                |
| 5. Serial Number                |                |
| 6. Customer Asset ID/Asset Name | Number 8 crane |

### Service Call Details






- |  |  |
|--|--|
| 7. Service Objectives                              |  |
| <i>Laser align brake between gearbox and motor</i> |  |

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

## 8. Services Performed

*We got the hoist to drop down the clamp hooks into the floor so we could do the alignment. Loosened off brake and checked alignment between the clutch and gearbox, then between the motor and clutch.*



## 9. Service Technician Recommendations

*The motor is about .230 thousandths high and the clutch is about .015 thousandths high. We can't get them any lower without removing the clutch and motor and doing extensive modifications to the bases. By the angle of the motor and the clutch both pointing at the angle they are and the coupling not showing any signs of wear from mis-alignment I decided that it is okay to run. The length of the run between everything really helps with the height issue.*

## Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

**Jack Smithson**

A handwritten signature in black ink, appearing to read 'Jack Smithson', is written over a light gray grid background.