

Field Service Ticket

City of Dequeen (12753) 125 City Shop Rd Dequeen, AR 71832 Hi-Speed Industrial Service 7030 Ryburn Dr Millington, Tn 38053 901-873-5300

> FolderID: 103002 FormID: 20745771

| Job Information | | Ō |
|----------------------|-------------------------------|-----------------|
| 1. | Hi-Speed Job Number | 103002 |
| 2. | Asset Type | split case pump |
| 3. | Make | P3 |
| 4. | Model | |
| 5. | Serial Number | |
| 6. | Customer Asset ID/Asset Name | Pump 2 |
| Service Call Details | | Ō |
| 7. | Service Objectives | |
| | Totally rebuild pump on site. | |

8. Services Performed P8

Removed top part of pump. We noticed the impellor is severely worn and the customer wants to have it replaced as well. After this pump is rebuilt the customer would like for us to check the larger pump next to it and go from there. Update. Rebuilt the pump assembly in the shop and went out to reinstall. Aligned motor to pump once pump was finished. Pump ran good pumping around 1400 gallons per minute.

















9. Service Technician Recommendations

Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.