



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103332
FormID: 21242693

Bryce Corporation (10053-BRC)
450 S. Benton
Searcy, AR 72143

Job Information



- | | | |
|------------------------|------------|----|
| 1. Hi-Speed Job Number | 103332 | |
| 2. Asset Type | 400 hp fan | |
| 3. Make | | P3 |



- | | | |
|----------|--|----|
| 4. Model | | P4 |
|----------|--|----|



- | | |
|---------------------------------|--|
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details



- | | |
|--|----|
| 7. Service Objectives | |
| <i>Wire and laser align motor to fan</i> | |
| 8. Services Performed | P8 |
| <i>Same as objective</i> | |



- | | |
|---------------------------------------|--|
| 9. Service Technician Recommendations | |
|---------------------------------------|--|

Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to be 'T. Hall', written in a cursive style.

11. Customer Signature

Ryan Fryrear

A handwritten signature in black ink, appearing to be 'Ryan Fryrear', written in a cursive style.