



Field Service Ticket

FolderID: 103337
FormID: 21253493

Arkansas Lime Company
600 Limesdale Rd
Batesville, AR 72501

Job Information



- | | |
|------------------------|--------|
| 1. Hi-Speed Job Number | 103337 |
| 2. Asset Type | Fan P2 |



- | |
|---------------------------------|
| 3. Make |
| 4. Model |
| 5. Serial Number |
| 6. Customer Asset ID/Asset Name |

Service Call Details



- | | |
|---|----|
| 7. Service Objectives
<i>Laser align new fan and motor.</i> | |
| 8. Services Performed
<i>Laser aligned motor to fan. Ended at 0,0,0,0.</i> | P8 |



- | |
|---|
| 9. Service Technician Recommendations
<i>Would do a hot alignment on it when you recheck the alignment after running at full temp.</i> |
|---|

Approval Signatures

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to read 'T. Hall', written in a cursive style.

11. Customer Signature

Landon Dilday

A handwritten signature in black ink, appearing to read 'L. Dilday', written in a cursive style.