

Field Service Ticket

Tolm Group Inc (12758) 210 N Moose St Morrilton, AR 72110 FolderID: 103285 FormID: 21518509

Job In	formation	
1.	Hi-Speed Job Number	103285
2.	Asset Type	150 hp hoffman blower motor
3.	Make	
4.	Model	
5.	Serial Number	
6.	Customer Asset ID/Asset Name	Blower 2
Servio	e Call Details	io i
7.	Service Objectives	
	Install motor, laser align to manufacturer specs.	
8.	Services Performed	F
	Same as objective.	
HOT ALLO		
9.	Service Technician Recommendations	
	val Signatures	
10.	Service Technician Signature	Trevor Hall

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Joel Thetford

Oel Å Z

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.