

LR Field Services

Prepared for Green Bay Packaging, Pinecrest (11362)

3610 Hwy 64 East
Plummerville AR 72127

Table of Contents

Balancing Report

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 09/30/2024

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Balancing Report

FolderID: 103546
FormID: 21773903

**Green Bay Packaging, Pinecrest
(11362)**
3610 Hwy 64 East
Plummerville, AR 72127

*Additional Notes: Assisted by: Ethan
Nutt*

General		
1. Job Number	103546	
2. Report Date	09/30/2024	
3. Customer	Green Bay	
Balancing Report		
4. Balance Type	single plane	
5. Balance Operating Speed	554 RPM	
6. Starting Measurements		
Left End	Right End	
4.7838	5.6283	
7. Balancing Specification	1.5	
8. Finished Measurements		
Left End	Right End	
0.2099	0.3165	
9. List Parts Needed <i>6- 237g clamp on weights</i>		
10. Service Technician	David Maclin	
		