

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 04/15/2024

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 102762
FormID: 20058248

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

Job Information

- | | |
|---------------------------------|------------------------|
| 1. Hi-Speed Job Number | 102762 |
| 2. Asset Type | multiple motors |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | | |
|---------------------------------------|--|
| 7. Service Objectives | <i>PDMA multiple motors</i> |
| 8. Services Performed | <i>Tested multiple motors with the PDMA machine. All data and pictures are in the PDMA report.</i> |
| 9. Service Technician Recommendations | |

Approval Signatures

- | | |
|----------------------------------|---------------------------------|
| 10. Service Technician Signature | David Maclin/Trevor Hall |
|----------------------------------|---------------------------------|

- | | |
|------------------------|----------------------|
| 11. Customer Signature | Michael Woole |
|------------------------|----------------------|