

LR Field Services

Prepared for AFPG Little Rock

11121 Richardson Drive
North Little Rock AR 72113

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104976
FormID: 25374068

AFPG Little Rock
11121 Richardson Drive
North Little Rock, AR 72113

Job Information

- | | |
|------------------------|-----------|
| 1. Hi-Speed Job Number | 104976 |
| 2. Asset Type | Fire pump |
| 3. Make | |





- | | |
|---------------------------------|-----------|
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | Fire pump |

Service Call Details

7. Service Objectives
To check motor.

8. Services Performed
Incoming power is good. 480, 481 and 480 volts. Amps full load are 93, 91 and 89. Motor is rated for 87 with 1.15 service factor. Motor runs great and the pump is pumping more water than it is rated for. The panel is starting to fall apart and rusty metal is falling onto the top of the contactors. Customer is going to request a new panel before it falls apart.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

Replace panel

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Jeffrey Hebert