

LR Field Services

Prepared for Dassault Falcon Jet (11751)

3801 East 10th st.
Little rock AR 72203

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 07/10/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104876
FormID: 25095855

Dassault Falcon Jet (11751)

3801 East 10th st.
Little rock, AR 72203

Job Information

- Hi-Speed Job Number **104876**
- Asset Type
Fan on roof
- Make
- Model
- Serial Number
- Customer Asset ID/Asset Name

Service Call Details

- Service Objectives
Balance fan after bearing change
- Services Performed



Initial reading fan side 11.7 mils Final reading fan side 0.5 mils

- Service Technician Recommendations

Approval Signatures

- Service Technician Signature **Shon Jones**

- Customer Signature **Porter Johnson**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.