



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103933
FormID: 22752785

Bryce Corporation (10053-BRC)

450 S. Benton
Searcy, AR 72143

Die Shop

Job Information



1. Hi-Speed Job Number **103933**
2. Asset Type **blower fan**
3. Make **P3**





4. Model
5. Serial Number
6. Customer Asset ID/Asset Name

Service Call Details



7. Service Objectives **P7**
Initial unbalance 11.9 mils inboard and 5.5 mils outboard. Final 0.1 inboard and 1.0 outboard



8. Services Performed
9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature **Shon Jones**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

11. Customer Signature

Shane Bitner

A handwritten signature in black ink, appearing to read "Shane Bitner", with a stylized, overlapping flourish at the end.