

## **Field Service Ticket**

Sol Alman Company (11708) 1300 E Ninth St Little Rock, AR 72203 FolderID: 103954 FormID: 22957475

Job In	formation				
1.	Hi-Speed Job Number			103954	
2.	Asset Type		excavator with	h magnet on boom	
3.	Make				
4.	Model				
5.	Serial Number				
6.	Customer Asset ID/Ass	et Name		Cat235/182	
Service Call Details					
7.	Service Objectives				
	Cat325/182. Send ticket	with this reference number or	ı it.		
8.	Services Performed				P8
	flash the fields multiple	times with motor not running Its on its own and would gene	) degrees. Motor only generated 5.5 volts at and did the same with motor running. It sta erate over 200 as long as I held it. Motor did	arted	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

 9. Service Technician Recommendations

 Pull motor and send to shop for further evaluation.

 Approval Signatures

 10. Service Technician Signature
 Trevor Hall

 Myles Bell

 11. Customer Signature
 Myles Bell

 Myles Bell

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.