

LR Field Services

Prepared for Highland Pellets (012194)

5601 Industrial Dr North
Pine Bluff AR 71602

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 05/20/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104624
FormID: 24510728

Highland Pellets (012194)

5601 Industrial Dr North
Pine Bluff, AR 71602

Job Information

- | | |
|---------------------------------|----------------------|
| 1. Hi-Speed Job Number | 104624 |
| 2. Asset Type | vibration- quarterly |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

- | |
|---|
| 7. Service Objectives |
| <i>Collect vibration data</i> |
| 8. Services Performed |
| <i>Walk through plant collecting data on online assets.</i> |
| 9. Service Technician Recommendations |
| <i>Welds broken on green hog</i> |



Approval Signatures

- | | |
|----------------------------------|------------|
| 10. Service Technician Signature | Shon Jones |
|----------------------------------|------------|

- | | |
|------------------------|--------------------|
| 11. Customer Signature | Raymond Calderwood |
|------------------------|--------------------|

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.