

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 01/13/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

FolderID: 103703
FormID: 23011471

Job Information

1. Hi-Speed Job Number	103703
2. Asset Type	Multiple motors
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives

Pull fan covers off of 9 motors to modify in shop.

8. Services Performed

Pulled blowers and fan covers off of 9 motors.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Dylan Holstead