

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents

Field Service Ticket	1.0
Field Service Ticket	2.0
General Machining/Fabrication Report	3.0



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103703
FormID: 23011471

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

Job Information

1. Hi-Speed Job Number	103703
2. Asset Type	Multiple motors
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives
Pull fan covers off of 9 motors to modify in shop.
8. Services Performed
Pulled blowers and fan covers off of 9 motors.



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Dylan Holstead



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 103703
FormID: 23106958

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

Job Information

1. Hi-Speed Job Number	103703
2. Asset Type	Multiple motors
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives

Install tachs, fan covers and cooling fan motors.

8. Services Performed

Same as objective



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

11. Customer Signature

Dylan Holstead



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

General Machining/Fabrication Report

FolderID: 103703
FormID: 23077120

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

General

1. Job Number
2. Description of Work to be Performed
Machine and install encoder brackets



3. Materials List
4. Drawings
5. Critical Dimensions
6. Machinist Signature

Gary And Chris

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 01/21/2025

Powered by **INSPECTALL**

3.0