

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 03/11/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104229
FormID: 23701541

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

Job Information

1. Hi-Speed Job Number **104229**

2. Asset Type



3. Make



4. Model

5. Serial Number

6. Customer Asset ID/Asset Name



Service Call Details

7. Service Objectives

*Balance fan running on vfd at 48 Hz.
Initial reading 3.0 and 2.3 mils*

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 03/11/2025

Powered by [INSPECTALL](#)

1.0



8. Services Performed
- Balance at 48 hHz .5 and 1.1 mils reading at max operating speed .9 and 2.0 mils unit will primarily operate at 48 Hz.



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature
- Shon Jones

11. Customer Signature
- Gammon Clark