

LR Field Services

Prepared for Kimberly Clark (10176-KCM)

500 Murphy Dr.
Maumelle AR 72113

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 07/24/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

Kimberly Clark (10176-KCM)
500 Murphy Dr.
Maumelle, AR 72113

FolderID: 104575
FormID: 25227940

Job Information

1. Hi-Speed Job Number	104575
2. Asset Type	Multiple motors
3. Make	
4. Model	
5. Serial Number	
6. Customer Asset ID/Asset Name	

Service Call Details

7. Service Objectives
To perform PDMA tests on 12 motors.
8. Services Performed
Performed PDMA tests on 12 motors.



Extruder 6 before



BWE 6 before



Extruder 6 after



BWE 5 before



Extruder 5 before



BWE 6 after



BWE 5 after



BWE 1 before



Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Extruder 5 after



BWE 2 before



BWE 1 after



Extruder 2 before



BWE 2 after



Picker 1 before



Extruder 2 after. L3 buss bar is loose inside the VFD



Extruder 1 after



Picker 2 before



Picker 5 before



Picker 6 before



Picker 1 after




Picker 2 after



Picker 5 after



Picker 6 after



9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature

Trevor Hall

A handwritten signature in black ink, appearing to read "Trevor Hall".

11. Customer Signature

Brian

A handwritten signature in black ink, appearing to read "Brian".