

LR Field Services

Prepared for NABCO Service Company

PO Box 1547
Conway AR 72033

Table of Contents

Field Service Ticket

1.0

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

Printed on 08/01/2025

Powered by [INSPECTALL](#)

Table of Contents



Hi-Speed Industrial Service
7030 Ryburn Dr
Millington, Tn 38053
901-873-5300

Field Service Ticket

FolderID: 104978
FormID: 25361977

NABCO Service Company
PO Box 1547
Conway, AR 72033

Job Information

- | | |
|---------------------------------|--------|
| 1. Hi-Speed Job Number | 104978 |
| 2. Asset Type | |
| 3. Make | |
| 4. Model | |
| 5. Serial Number | |
| 6. Customer Asset ID/Asset Name | |

Service Call Details

7. Service Objectives
Align 2 motor to pump
8. Services Performed



TCWP 1B as left



TCWP 1B as found



TVWP 1A as left



TCWP 1A as found

9. Service Technician Recommendations

Approval Signatures

10. Service Technician Signature **Shon Jones**

11. Customer Signature **William Homman**

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.