

# LR Field Services

Prepared for Riceland Foods-Hazen (10247-09)

1101 Riceland Street  
Hazen AR 72160

# Table of Contents

Balancing Report	1.0
Field Service Ticket	2.0



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Balancing Report

FolderID: 104717  
FormID: 24694276

**Riceland Foods-Hazen (10247-09)**

1101 Riceland Street  
Hazen, AR 72160

<b>General</b>		
1.	Job Number	
2.	Report Date	
3.	Customer	
<b>Balancing Report</b>		
4.	Balance Type	
5.	Balance Operating Speed	
6.	Starting Measurements	
	Left End	Right End
7.	Balancing Specification	
8.	Finished Measurements	
	Left End	Right End
9.	List Parts Needed	
10.	Service Technician	

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.



Hi-Speed Industrial Service  
7030 Ryburn Dr  
Millington, Tn 38053  
901-873-5300

## Field Service Ticket

FolderID: 104717  
FormID: 24694277

**Riceland Foods-Hazen (10247-09)**  
1101 Riceland Street  
Hazen, AR 72160

### Job Information

- |                        |         |
|------------------------|---------|
| 1. Hi-Speed Job Number | 104717  |
| 2. Asset Type          | NYB fan |
| 3. Make                |         |
| 4. Model               |         |



- |                                 |  |
|---------------------------------|--|
| 5. Serial Number                |  |
| 6. Customer Asset ID/Asset Name |  |

### Service Call Details

7. Service Objectives

*To balance fan*

8. Services Performed

*I pulled the inspection cover to inspect the fan and noticed that something had ran through it and the fan is coming apart. I offered to help fix the fan on site but the customer wants to check on a new fan and said he will get back with us once he makes a decision.*



9. Service Technician Recommendations

*Fix or replace fan wheel.*

Hi-Speed Industrial Service disclaims all warranties, both express and implied, relating to the information, reports, opinions and analysis disclosed to the Customer by Hi-Speed. Hi-Speed shall not be liable for any errors or omissions, or any losses, injury or damages arising from the use of such information, reports, opinions and analysis by the Customer.

## Approval Signatures

10. Service Technician Signature

**Trevor Hall**



11. Customer Signature

**Tim Harper**

